

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION 5** 77 WEST JACKSON BOULEVARD

CHICAGO, ILLINOIS 60604

DATE:

DEC 0 5 2019

SUBJECT:

CLEAN AIR ACT INSPECTION REPORT

DNR Customs, LLC, Casco, Michigan

FROM:

Cody Yarbrough, Environmental Engineer

AECAB (MN/OH)

THRU:

Brian Dickens, Section Chief

AECAB (MN/OH)

TO:

File

BASIC INFORMATION

Facility Name: DNR Customs, LLC

Facility Location: 9568 Marine City Hwy Casco, Michigan 48064

Date of Inspection: October 30, 2019

EPA Inspector(s):

1. Cody Yarbrough, Environmental Engineer

Other Attendees

1. Derek Rose, Owner, DNR Customs

2. Nicole Rose, Shop Manager, DNR Customs

Contact Email Address: info@dnrcustoms.com

Purpose of Inspection: Emission control device tampering on vehicles and engines.

Facility Type: Vehicle repair and performance shop.

Regulations Central to Inspection: Emission control device tampering prohibitions. CAA

Section 203(a)(3)(a)-(b).

Arrival Time: 10:25 AM, CDT Departure Time: 11:35 AM. CDT

Inspection Type:

☐ Unannounced Inspection

☐ Announced Inspection

OPENING CONFERENCE

☐ CBI warning to facility provided

The following information was obtained verbally from Mr. Rose unless otherwise noted.

Process Description:

DNR Customs has been in business since approximately 2006 and specializes in diesel performance and repair work. They primarily conduct diagnostics and engine and transmission repair, though they conduct some performance work on competition vehicles (truck pulls, drag races, etc.) and sell products online as well.

Staff Interview: When Mr. Yarbrough arrived, Ms. Rose requested that he wait in the lobby until Mr. Rose arrived, approximately ten minutes later. Mr. Rose then provided a tour of the facility. Mr. Rose stated that DNR Customs has performed deletes in the past but stopped doing this work approximately six months earlier, and this resulted in a significant loss of revenue for his business. He estimated the last emissions delete performed by his shop was around April or May of 2019.

TOUR INFORMATION

EPA toured the facility: Yes

Data Collected and Observations:

The lobby of the shop contained banners for various aftermarket products including BD Diesel Performance, Maryland Diesel Performance, and Flo~Pro. Mr. Rose stated that DNR Customs no longer uses products from Maryland Diesel Performance or Flo~Pro and uses primarily injectors and transmission parts from BD Diesel Performance.

Two Ford pickup trucks were observed onsite with aftermarket exhaust systems. Both appeared to have no exhaust aftertreatment systems. These are listed in Appendix B.

Photos and/or Videos: were taken during the inspection.

Field Measurements: were not taken during this inspection.

CLOSING CONFERENCE

Compliance Assistance: Provided general compliance assistance regarding emission control device tampering, work performed on tampered vehicles, and sales of aftermarket defeat devices.

Concerns: Mr. Yarbrough expressed concern regarding performance work and sales of parts that affect vehicle emissions, especially for work and parts that remove emission control devices.

SIGNATURES

Report Author: Cosh Ysbrigh Date: 12-5-19

Section Chief: Buller Disturb Date: 12/5-/19

Facility Name: DNR Customs, LLC

Facility Location: 9568 Marine City Hwy Casco, MI 48064

Date of Inspection: October 30, 2019

APPENDICES AND ATTACHMENTS

1. Appendix A: Digital Image Log

2. Appendix B: Vehicle Inspection Summary

Facility Name: DNR Customs, LLC

Facility Location: 9568 Marine City Hwy Casco, MI 48064

Date of Inspection: October 30, 2019

APPENDIX A: DIGITAL IMAGE LOG

| 1. Inspector Name: Cody Yarbrough | 2. Archival Record Location: CD-R labeled "DNR |
|-----------------------------------|--|
| | Customs Inspection Photos 10-30-19" |

| Image Number | File Name | Date and Time (CDT) | Description of Image |
|--------------|--------------|------------------------|---------------------------|
| 4 | | 2019:10:30 | |
| 1 | PA300073.JPG | 11:04:11 | Shop floor exhaust pieces |
| | | 2019:10:30 | |
| 2 | PA300074.JPG | 11:10:42 | Truck 1 rear |
| | | 2019:10:30 | |
| 3 | PA300075.JPG | 11:10:54 | Truck 1 exhaust |
| | | 2019:10:30 | |
| 4 | PA300076.JPG | 11:11:33 | Truck 2 rear |
| | | 2019:10:30 | |
| 5 | PA300077.JPG | 11:11:39 | Truck 2 exhaust tip |
| | | 2019:10:30 | |
| 6 | PA300078.JPG | 11:11:46 | Truck 2 exhaust |
| | | 2019:10:30 | |
| 7 | PA300079.JPG | 11:12:04 | Truck 2 VIN sticker |

Facility Name: DNR Customs, LLC

Facility Location: 9568 Marine City Hwy Casco, MI 48064

Date of Inspection: October 30, 2019

APPENDIX B: FIELD MEASUREMENT DATA

| Vehicles Inspected/Obse | erved | Leave . | | 5250 |
|-------------------------|-----------------|------------------|-------------|--------------------------------|
| | | Appearance of | OBD Data | |
| | | Tampering | Obtained | Observations (e.g., Who |
| | | (Yes/No/TB | ? | Performed Apparent |
| VIN | Vehicle Model | D) | (Yes/No) | Tampering?) |
| | | | | Aftermarket exhaust with no |
| 1FTSW21P56ED55286 | 2006 Ford F-250 | | | aftertreatment. Unknown source |
| License: DHK 2842 | Super Duty | Yes | No | of tampering. |
| | , | | | Aftermarket exhaust with no |
| | 2005 Ford F-250 | | | aftertreatment. Unknown source |
| License: CJU 8372 | Super Duty | Yes | No | of tampering. |